



3310-C Gilmore Industrial Boulevard
Louisville, Kentucky 40213

Phone (502) 964-8737
Facsimile (502) 964-1123

Facility Asbestos Inspection

Facility: 509 E. Oak Street **Inspection Date:** 8/6/2010
Location: New Albany, IN **Inspector:** Welsh, Pete

Micro-Analytics, Inc. conducted a facility asbestos inspection at the facility identified above on the date indicated. The asbestos inspection was performed in accordance with the EPA recommended protocol for a facility asbestos inspection.

During the site inspection, suspect asbestos-containing materials were grouped into homogeneous areas (HA's), with any given homogeneous area being a material exhibiting the same color, texture, and physical appearance. Each suspect homogeneous areas were then sampled in accordance with EPA protocol, and each sample collected was given a unique identification number.

Collected samples were then analyzed by an AIHA accredited laboratory using Polarized Light Microscopy (PLM) and the dispersion staining technique, which is the EPA-approved method for the analysis of bulk materials for the presence of asbestos.

This report summarizes the findings of the facility inspection. The report includes:

- An Asbestos Materials Summary Form, which details all of the asbestos-containing materials that were discovered during the inspection.
 - A Homogeneous Area Summary Form, which details all HA's that were identified during the inspection and includes both asbestos-containing materials and non-asbestos materials.
 - A Facility Drawing which shows locations of the samples collected and identifies the areas where asbestos materials are present in the facility.
 - A Bulk Analysis Report, which shows the analytical results from the laboratory for the PLM analysis.
-

Facility Asbestos Inspection – Summary of Asbestos-Containing Materials

Facility: 509 E. Oak Street

Date of Inspection: 8/6/2010

Location New Albany, IN

Inspector: Welsh, Pete

HA No.	Material Type	Description	Locations of Material	Material Quantity (ft ²)	Condition of ACM	Asbestos Type and Percent
05	Misc	Roof Coating	Exterior	1194	Damaged	5-7% Chrysotile
08	Misc	Exterior Siding (Transite)	Exteior	1600	Damaged	15-20% Chrysotile

Facility Asbestos Inspection – Summary of Homogeneous Areas

Facility: 509 E. Oak Street


Date of Inspection: 8/6/2010

Location New Albany, IN

Inspector: Welsh, Pete

HA No.	Material Type	Description	Locations of Material	Material Quantity (ft ²)	Sample Numbers	Is Asbestos Present?
01	Misc	Drywall and Mud	Living Room	Throughout	1	No
02	Misc	Plaster	Dining Room	Throughout	2	No
03	Misc	Textured Ceiling	Bathroom	Throughout	3	No
04	Misc	Window Glazing	Exterior	2 Windows	4	No
05	Misc	Roof Coating	Exterior	1194	5	Yes
06	Misc	Shingle (Bottom Layer)	Exterior, Kitchen Roof	144	6	No
07	Misc	Shingle (Top Layer)	Exterior, Kitchen Roof	144	7	No
08	Misc	Exterior Siding (Transite)	Exterior	1600	8	Yes
09	Misc	Exterior Siding (Tar Paper)	Exterior	1600	9	No
10	Misc	Floor Sheeting	Utility	120	10	No
11	Misc	Floor Tile	Kitchen	50	11	No

Floor Plan Drawings



Micro-Analytics, Inc.
3310-C Gilmore Industrial
Blvd.
Louisville, KY 40213
(502)964-8737

509 E. Oak Street, New Albany, IN

Project #	Drawn by	Scale	Date
62833	N. Leow	NTS	August 10, 2010

MRS Analytical Laboratory, Inc.

Bulk Asbestos Report

Project Number: 62833 **Date Received:** 8/10/2010
Client: New Directions Housing Corporation **Date Reported:** 8/10/2010
Facility: 509 E. Oak Street **Analysis Date:** 8/10/2010
Sample Type: Bulk Material **Analyst:** John Holley
Date Sampled: 8/6/2010 **Sampled By:** Pete Welsh

TEST DESCRIPTION: Analysis of Bulk Material for Asbestos.

ANALYTICAL METHOD: Polarized Light Microscopy with Dispersion Staining as Defined in 40 CFR, Part 763, Subpart F, Appendix A.


<i>Micro-Analytcs Sample Number</i>	<i>Client Sample Number and Laboratory Gross Description</i>	<i>Type and Percent Asbestos</i>
1.1	Drywall/Mud	NAD
1.2	Drywall/Mud	NAD
1.3	Drywall/Mud	NAD
2.1	Plaster	NAD
2.2	Plaster	NAD
2.3	Plaster	NAD
3.1	Textured Ceiling	NAD
3.2	Textured Ceiling	NAD
3.3	Textured Ceiling	NAD
4.1	Window Glazing	NAD
4.2	Window Glazing	NAD
4.3	Window Glazing	NAD
5.1	Roof Coating	5-7% Chrysotile
5.2	Roof Coating	5-7% Chrysotile
5.3	Roof Coating	5-7% Chrysotile
6.1	Roof Shingle- Bottom Layer	NAD
6.2	Roof Shingle- Bottom Layer	NAD
6.3	Roof Shingle- Bottom Layer	NAD

Reporting Limit 1% Asbestos

NAD: No Asbestos Detected

MRS Analytical Laboratory, Inc., is accredited and certified Proficient by the American Industrial Hygiene Association – Accreditation Number: AIHA-102459

Reviewed by Authorized Signatory



MRS Analytical Laboratory, Inc.

Bulk Asbestos Report

Project Number: 62833 **Date Received:** 8/10/2010
Client: New Directions Housing Corporation **Date Reported:** 8/10/2010
Facility: 509 E. Oak Street **Analysis Date:** 8/10/2010
Sample Type: Bulk Material **Analyst:** John Holley
Date Sampled: 8/6/2010 **Sampled By:** Pete Welsh

TEST DESCRIPTION: Analysis of Bulk Material for Asbestos.

ANALYTICAL METHOD: Polarized Light Microscopy with Dispersion Staining as Defined in 40 CFR, Part 763, Subpart F, Appendix A.

<i>Micro-Analytcs Sample Number</i>	<i>Client Sample Number and Laboratory Gross Description</i>	<i>Type and Percent Asbestos</i>
7.1	Roof Shingle- Top Layer	NAD
7.2	Roof Shingle- Top Layer	NAD
7.3	Roof Shingle- Top Layer	NAD
8.1	Exterior Siding (Transite)	15-20% Chrysotile
8.2	Exterior Siding (Transite)	15-20% Chrysotile
8.3	Exterior Siding (Transite)	15-20% Chrysotile
9.1	Exterior Siding (Tar Paper)	NAD
9.2	Exterior Siding (Tar Paper)	NAD
9.3	Exterior Siding (Tar Paper)	NAD
10.1	Floor Sheeting	NAD
10.2	Floor Sheeting	NAD
10.3	Floor Sheeting	NAD
11.1	Floor Tile	NAD
11.1m	Tan Glue on 11.1	NAD
11.2	Floor Sheeting	NAD
11.2m	Tan Glue on 11.2	NAD
11.3	Floor Sheeting	NAD
11.3m	Tan Glue on 11.3	NAD

Reporting Limit 1% Asbestos

NAD: No Asbestos Detected

MRS Analytical Laboratory, Inc., is accredited and certified Proficient by the American Industrial Hygiene Association – Accreditation Number: AIHA-102459

Reviewed by Authorized Signatory

